
Formerly Utilized Sites Remedial Action Program (FUSRAP)

ADMINISTRATIVE RECORD

for Maywood, New Jersey



U.S. Department of Energy

Bechtel

Oak Ridge Corporate Center
151 Lafayette Drive
P.O. Box 350
Oak Ridge, Tennessee 37831-0350

Facsimile: (615) 220-2100

Board of Health
Maywood Borough Hall
459 Maywood Avenue
Maywood, New Jersey 07607

Job No. 14501, FUSRAP Project
DOE Contract No. DE-AC05-91OR21949
Code: 2570 /WBS: 138

NOV 29 1995

Attention: Mary Carton, Health Inspector
Maywood Board of Health

Subject: Maywood Site - Information Requested at Safety Briefing

Dear Ms. Carton:

Thank you for the opportunity to provide a briefing concerning prudent work routines at properties in the Maywood area designated under the Department of Energy's (DOE) Formerly Utilized Sites Remedial Action Program.

Enclosed are materials you requested at the briefing to give you a better idea of where radioactive material may exist at the properties. The legends on the drawings indicate the color codings.

It is always a pleasure to work with representatives of the borough and people in the Maywood community.

If you have any questions, please give me a call at (423) 576-4718. Or you can call DOE's toll free information line at 1-800-253-9759 and leave your name, phone number, and message, and someone will return your call promptly.

Sincerely,



M. E. Redmon
Project Manager - FUSRAP

NJ_0652.doc

Enclosure: Drawings of Properties

Concurrence: J. S. Herron @ 

L. W. Scarbrough 

ACTION REQ'D	<input type="checkbox"/> YES	<input checked="" type="checkbox"/> NO	DUE DATE _____
RESPONSE TO CHRON NO. _____			
<input type="checkbox"/> FFA	<input type="checkbox"/> Permit	<input type="checkbox"/> Milestone	<input type="checkbox"/> OcR <input type="checkbox"/> CCN <input type="checkbox"/> CAR <input type="checkbox"/> Mid-Yr <input type="checkbox"/> Yr-End <input type="checkbox"/> Periodic Rpt



Bechtel National, Inc.

FIGURES ATTACHED WITH LETTER TO MARY CARTON IN NOVEMBER, 1995

R43F008.DGN

Figure 4 - 34

PIC Measurement Locations and Areas of Contamination at the
DeSaussure Property 23 West Howcroft Avenue

R43F007.DGN

Figure 4 - 32

PIC Measurement Locations and Areas of Contamination at the
Former Appleton Electric Property 100 Hancock Street

R43F006.DGN

Figure 4 - 30

PIC Measurement Locations and Areas of Contamination at
Airco Medical and Specialty Products 80 Hancock Street

R43F005.DGN

Figure 4 - 6

PIC Measurement Locations and Areas of Contamination at the
Former Hunter Douglas Property 85-99 Route 17 North

R43F004.DGN

Figure 4 - 1

PIC Measurement Locations and Areas of Contamination
at National Community Bank 160 and 174 Essex Street

R43F003.DGN

Figure 4 - 41

PIC Measurement Locations and Areas of Contamination at the
Sears Distribution Center Property 149-151 Maywood Avenue

R43F002.DGN

Figure 4 - 10

PIC Measurement Locations and Areas of Contamination
at the Gulf Station Property 239 Route 17 North

R43F019.DGN

Figure 4 - 51

PIC Measurement Locations and Areas of Contamination at the
Fire Station No. 2 Property Kennedy Drive and Brook Street

R43F018.DGN

Figure 4 - 53

PIC Measurement Locations and Areas of Contamination at John F. Kennedy Park
Kennedy Drive and Money Street

R43F017.DGN

Figure 4 - 28

PIC Measurement Locations and Areas of Contamination at the
Bergen Cable Property 170 Gregg Street

R43F016.DGN

Figure 4 - 12

PIC Measurement Locations and Areas of Contamination at the
Stepan Property 100 West Hunter Avenue

R43F015.DGN

Figure 4 - 44

PIC Measurement Locations and Areas of Contamination at the
Myron Manufacturing Properties
50 and 61 West Hunter Avenue and 205 Maywood Avenue

R43F014.DGN

Figure 4 - 3

PIC Measurement Locations and Areas of Contamination at
National Community Bank 113 Essex Street

R43F013.DGN

Figure 4 - 39

PIC Measurement Locations and Areas of Contamination at
Sears Repair Center Property 200 State Route 17 South

R43F012.DGN

Figure 4 - 36

PIC Measurement Locations and Areas of Contamination at the
Joseph Muscarelle Property
Essex Street and State Route 17

R43F011.DGN

Figure 4 - 49

PIC Measurement Locations and Areas of Contamination
at the New Jersey Vehicle Inspection Station Property
8 Mill Street

R43F010.DGN

Figure 4 - 22
PIC Measurement Locations and Areas of Contamination at the
Sunoco Station Property 167 Route 17 North

R43F009.DGN

Figure 4 - 24
PIC Measurement Locations and Areas of Contamination at the
Former Federal Express Property 137 Route 17 North

R43F001.DGN

Figure 4 - 26
PIC Measurement Locations and Areas of Contamination at the
Flint Ink Property 80 Industrial Road

M38W9818.DGN

Figure 5 - 2
Areas of Subsurface Contamination at I-80
(Eastbound Right-Of-Way)

-0-

Figure 2
Boundaries of the Surface Contamination on the
Embankments of Route 17

M38W9818.DGN

Figure 5 - 1
Areas of Surface Contamination along I-80
(Eastbound Right-Of-Way)

M38W9854.DGN

Figure 5 - 1
Areas of Subsurface Contamination at 72 Sidney Street

138VPBAS.DGN

Figure 1
Maywood Vicinity Properties
Contamination Boundaries
After 3/95 Sampling Effort