

M-344
117936 01

Formerly Utilized Sites Remedial Action Program (FUSRAP)

ADMINISTRATIVE RECORD

for Maywood, New Jersey



U.S. Department of Energy



94-399

117936

Department of Energy

Oak Ridge Operations
P.O. Box 2001
Oak Ridge, Tennessee 37831-8723

July 1, 1994

Mr. Jeffrey Gratz
Federal Facilities Section
U.S. Environmental Protection Agency
Region II
Jacob K. Javits Federal Building
26 Federal Plaza
New York, New York 10278

Dear Mr. Gratz:

MAYWOOD AND WAYNE SITES - DERIVATION OF URANIUM CLEANUP GUIDELINES

The purpose of this letter is to transmit three copies each of the subject reports. After applying the "as low as reasonably achievable" policy to the derived guidelines in these reports, as well as considering other factors such as contaminant distribution and instrument capabilities, DOE is recommending a uranium cleanup guideline of 100 pCi/g total uranium at each site. After cleanup, residual concentrations are expected to be significantly lower than the guideline since the site's characterization data shows that the uranium is co-located with thorium-232 at approximately the same concentrations.

If you have any questions or comments, please contact me at (615) 576-5724.

Sincerely,

A handwritten signature in cursive script that reads "Susan M. Cange".

Susan M. Cange, Site Manager
Former Sites Restoration Division

Enclosure See Administrative Record Document # M-710



Department of Energy

94-399 117936

Oak Ridge Operations
P.O. Box 2001
Oak Ridge, Tennessee 37831-8723

July 1, 1994

Mr. Nicholas Marton
Bureau of Federal Case Management
New Jersey Department of Environmental
Protection and Energy
Division of Hazardous Waste Management
401 E State Street
CN 028
Trenton, New Jersey 08625-0028

Dear Mr. Marton:

MAYWOOD AND WAYNE SITES - DERIVATION OF URANIUM CLEANUP GUIDELINES

The purpose of this letter is to transmit three copies each of the subject reports. After applying the "as low as reasonably achievable" policy to the derived guidelines in these reports, as well as considering other factors such as contaminant distribution and instrument capabilities, DOE is recommending a uranium cleanup guideline of 100 pCi/g total uranium at each site. After cleanup, residual concentrations are expected to be significantly lower than the guideline since the site's characterization data shows that the uranium is co-located with thorium-232 at approximately the same concentrations.

If you have any questions or comments, please contact me at (615) 576-5724.

Sincerely,

A handwritten signature in cursive script that reads "Susan M. Cange".

Susan M. Cange, Site Manager
Former Sites Restoration Division

Enclosure